

Rating Code	Condition Rating	Performance Rating	Priority Rating
0			Not a priority
1	New or Excellent - None or minor defects.	Exceeds/Meets all performance targets.	It would be nice to have.
2	Good - Defects that have not begun to deteriorate.	Minor performance deficiencies.	Improved system operations & maintenance (O&M) efficiency.
3	Fair - Moderate defects that will continue to deteriorate.	Considerable performance deficiencies.	Internal safety concern or public nuisance.
4	Poor - Severe defects that will collapse/break in near future.	Major performance deficiencies.	Potential public health, safety, or environmental concern.
5	Inoperable - Defects need immediate attention.	Fails to meet performance targets.	Existing threat to public health, safety, or environment.

**Sewer Line Assets**

Size (inches)	Type	Material	Decade Constructed	Length (feet)	Condition ID	Performance ID	Priority ID	WRIS PNum
<b>Assessment Area: ISLAND EAST ZONE</b>								
Up to 2	Gravity	PVC	1980	399	3			
4	Gravity	PVC	1980	5,931	2	2	1	
<b>Assessment Area: ISLAND NORTH ZONE</b>								
Up to 2	Force	PVC	1980	989	2	2	1	
4	Gravity	PVC	1980	6,325	2	2	1	
6	Force	PVC	1980	18,375	3			
<b>Assessment Area: ISLAND SOUTH ZONE</b>								
Up to 2	Gravity	PVC	1980	793	3			
4	Force	PVC	1980	6,157	3			
6	Gravity	PVC	1980	1,206	2	2	1	
<b>Assessment Area: ISLAND WEST ZONE</b>								
Up to 2	Gravity	PVC	1980	129	3			
4	Gravity	PVC	1980	9,651	2	2	1	
6	Gravity	PVC	1980	6,642	2	2	1	

## WRIS Asset Inventory Report KY0066605 - Island Water Department

Rating Code	Condition Rating	Performance Rating	Priority Rating
0			Not a priority
1	New or Excellent - None or minor defects.	Exceeds/Meets all performance targets.	It would be nice to have.
2	Good - Defects that have not begun to deteriorate.	Minor performance deficiencies.	Improved system operations & maintenance (O&M) efficiency.
3	Fair - Moderate defects that will continue to deteriorate.	Considerable performance deficiencies.	Internal safety concern or public nuisance.
4	Poor - Severe defects that will collapse/break in near future.	Major performance deficiencies.	Potential public health, safety, or environmental concern.
5	Inoperable - Defects need immediate attention.	Fails to meet performance targets.	Existing threat to public health, safety, or environment.

### Lift Station Assets

Asset Name	Date of Last Maintenance	Date of Next Maintenance	Capacity (GPM)	Pump Count	Condition ID	Performance ID	Priority ID	WRIS PNum
<b>Assessment Area: ISLAND EAST ZONE</b>								
HWY 85 LIFT STATION	02-28-2018	03-28-2018		2	2	2	1	
<b>Assessment Area: ISLAND SOUTH ZONE</b>								
431	02-28-2018	03-28-2018		2	3	2	2	

## WRIS Asset Inventory Report KY0066605 - Island Water Department

Rating Code	Condition Rating	Performance Rating	Priority Rating
0			Not a priority
1	New or Excellent - None or minor defects.	Exceeds/Meets all performance targets.	It would be nice to have.
2	Good - Defects that have not begun to deteriorate.	Minor performance deficiencies.	Improved system operations & maintenance (O&M) efficiency.
3	Fair - Moderate defects that will continue to deteriorate.	Considerable performance deficiencies.	Internal safety concern or public nuisance.
4	Poor - Severe defects that will collapse/break in near future.	Major performance deficiencies.	Potential public health, safety, or environmental concern.
5	Inoperable - Defects need immediate attention.	Fails to meet performance targets.	Existing threat to public health, safety, or environment.

### Sewer Treatment Plants

STP Name	Design Capacity (MGD)	Date Constructed	Major Expansion Date	Condition ID	Performance ID	Priority ID	WRIS PNum
ISLAND WASTEWATER TREATMENT PLANT	0.12800000	11/30/1983		3			

#### Treatment Plant Components:

Component Name	Date of Last Maintenance	Date of Next Maintenance	Condition ID	Performance ID	Priority ID	WRIS PNum
Control Building			3	2	1	