

WRIS Asset Inventory Report

KY0091731 - Sacramento Water Works

Rating Code	Condition Rating	Performance Rating	Priority Rating
0			Not a priority
1	New or Excellent - None or minor defects.	Exceeds/Meets all performance targets.	It would be nice to have.
2	Good - Defects that have not begun to deteriorate.	Minor performance deficiencies.	Improved system operations & maintenance (O&M) efficiency.
3	Fair - Moderate defects that will continue to deteriorate.	Considerable performance deficiencies.	Internal safety concern or public nuisance.
4	Poor - Severe defects that will collapse/break in near future.	Major performance deficiencies.	Potential public health, safety, or environmental concern.
5	Inoperable - Defects need immediate attention.	Fails to meet performance targets.	Existing threat to public health, safety, or environment.

Sewer Line Assets

Size (inches)	Type	Material	Decade Constructed	Length (feet)	Condition ID	Performance ID	Priority ID	WRIS PNum
Assessment Area: SACRAMENTO GRAVITY ZONE								
Up to 2	Force	PVC	1980	2,850	3			
3	Force	PVC	1980	344	3			
6	Gravity	PVC	1980	2,193	3			
8	Gravity	PVC	2010	3,389	2			
Assessment Area: SACRAMENTO GRINDER ZONE								
Up to 2	Force	PVC	1980	39,225	3			
3	Force	PVC	1980	4,022	3			
4	Force	PVC	1980	17,741	3			
6	Force	PVC	1980	12,437	3			
8	Force	PVC	2010	31	2			

WRIS Asset Inventory Report KY0091731 - Sacramento Water Works

Rating Code	Condition Rating	Performance Rating	Priority Rating
0			Not a priority
1	New or Excellent - None or minor defects.	Exceeds/Meets all performance targets.	It would be nice to have.
2	Good - Defects that have not begun to deteriorate.	Minor performance deficiencies.	Improved system operations & maintenance (O&M) efficiency.
3	Fair - Moderate defects that will continue to deteriorate.	Considerable performance deficiencies.	Internal safety concern or public nuisance.
4	Poor - Severe defects that will collapse/break in near future.	Major performance deficiencies.	Potential public health, safety, or environmental concern.
5	Inoperable - Defects need immediate attention.	Fails to meet performance targets.	Existing threat to public health, safety, or environment.

Lift Station Assets

Asset Name	Date of Last Maintenance	Date of Next Maintenance	Capacity (GPM)	Pump Count	Condition ID	Performance ID	Priority ID	WRIS PNum
Assessment Area: SACRAMENTO GRAVITY ZONE								
WEST 5TH ST			100	2	3			
Assessment Area: SACRAMENTO GRINDER ZONE								
HWY 85 E			100	2	3			

WRIS Asset Inventory Report KY0091731 - Sacramento Water Works

Rating Code	Condition Rating	Performance Rating	Priority Rating
0			Not a priority
1	New or Excellent - None or minor defects.	Exceeds/Meets all performance targets.	It would be nice to have.
2	Good - Defects that have not begun to deteriorate.	Minor performance deficiencies.	Improved system operations & maintenance (O&M) efficiency.
3	Fair - Moderate defects that will continue to deteriorate.	Considerable performance deficiencies.	Internal safety concern or public nuisance.
4	Poor - Severe defects that will collapse/break in near future.	Major performance deficiencies.	Potential public health, safety, or environmental concern.
5	Inoperable - Defects need immediate attention.	Fails to meet performance targets.	Existing threat to public health, safety, or environment.

Sewer Treatment Plants

STP Name	Design Capacity (MGD)	Date Constructed	Major Expansion Date	Condition ID	Performance ID	Priority ID	WRIS PNum
SACRAMENTO WASTEWATER TREATMENT PLANT	0.06200000	11/30/1988		2			

Treatment Plant Components:

--