

## WRIS Asset Inventory Report KY0025844 - Uniontown Water/Sewer Department



Rating Code	Condition Rating	Performance Rating			Priority Rating				
0					Not a priority				
1	New or Excellent - None or minor defects.	Exc	ceeds/Meets all per	formance targets.		It would be nice to have.			
2	Good - Defects that have not begun to deteriorate.	Mir	nor performance de	eficiencies.		Improved system operations & maintenance (O&M) efficiency.			
3	Fair - Moderate defects that will continue to deteriorate.	Co	Considerable performance deficiencies.			Internal safety concern or public nuisance.			
4	Poor - Severe defects that will collapse/break in near future.	Ма	jor performance de	eficiencies.		Potential public health, safety, or environmental concern.			
5	Inoperable - Defects need immediate attention.	Fai	Is to meet perform	ance targets.		Existing threat to public health, safety, or environment.			
			Sewer Lin	e Assets					
Size			Decade	Length	Conditio	n Performnce	Priority	WRIS	

5	тпорегавіе - і	Defects need immediate attention.	Falls to meet performance targets.			environment.			
Sewer Line Assets									
Size (inches)	Туре	Material	Decade Constructed	Length (feet)	Condition ID	Performnce ID	Priority ID	WRIS PNum	
Assessme	nt Area: UT	ZONE 1							
4	Force	CAST IRON	Prior to 1950	8	4				
4	Force	PVC	2000	5,163	2				
6	Gravity	CAST IRON	Prior to 1950	4,632	4				
8	Gravity	CAST IRON	Prior to 1950	7,646	4				
Assessme	nt Area: UT	ZONE 2							
6	Force	CAST IRON	Prior to 1950	Prior to 1950 215					
8	Gravity	CAST IRON	Prior to 1950	8,733	4				
Assessme	nt Area: UT	ZONE 3							
Up to 2	Force	PVC	1990	323	2				
4	Force	PVC	Unknown	782	3				
4	Gravity	PVC	2000	475	2				
6	Force	CAST IRON	Prior to 1950	3,773	4				
6	Gravity	PVC	1990	1,958	2				
6	Gravity	PVC	2000	401	2				
8	Gravity	CAST IRON	Prior to 1950	9,096	4				
Ssessme	nt Area: UT	ZONE 4							
4	Force	CAST IRON	Prior to 1950	33	4				
6	Gravity	PVC	1990	104	2				
6	Force	PVC	2000	6,423	2				
8	Gravity	CAST IRON	Prior to 1950	7,186	4				
Assessme	nt Area: UT	ZONE 5							
4	Force	PVC	Unknown	233	3				
4	Force	PVC	2000	16,385	2				



## WRIS Asset Inventory Report KY0025844 - Uniontown Water/Sewer Department



Rating Code	Condition Rating	Performance Rating	Priority Rating		
0			Not a priority		
1	New or Excellent - None or minor defects.	Exceeds/Meets all performance targets.	It would be nice to have.		
2	Good - Defects that have not begun to deteriorate.	Minor performance deficiencies.	Improved system operations & maintenance (O&M) efficiency.		
3	Fair - Moderate defects that will continue to deteriorate.	Considerable performance deficiencies.	Internal safety concern or public nuisance.		
4	Poor - Severe defects that will collapse/break in near future.	Major performance deficiencies.	Potential public health, safety, or environmental concern.		
5	Inoperable - Defects need immediate attention.	Fails to meet performance targets.	Existing threat to public health, safety, or environment.		

			Chinomica						
Lift Station Assets									
Asset Name	Date of Last Maintenance	Date of Next Maintenance	Capacity (GPM)	Pump Count	Condition ID	Performnce ID	Priority ID	WRIS PNum	
Assessment Area: UT ZONE 1									
BALL PARK STATION				2	3				
RIVERVIEW COAL			93	2	3				
YOUNG STREET LIFT STATION				2	3				
Assessment Area: UT ZONE 2									
MAIN STREET				2	3				
Assessment Area: UT ZONE 3									
RUARK DR				2	3				
Assessment Area: UT ZONE 4									
ADAMS STREET				2	3				
Assessment Area: UT ZONE 5									
PREP PLANT			31	2	3				



## WRIS Asset Inventory Report KY0025844 - Uniontown Water/Sewer Department



Condition Rating	Performance Rating	Priority Rating		
		Not a priority		
New or Excellent - None or minor defects.	Exceeds/Meets all performance targets.	It would be nice to have.		
Good - Defects that have not begun to deteriorate.	Minor performance deficiencies.	Improved system operations & maintenance (O&M) efficiency.		
Fair - Moderate defects that will continue to deteriorate.	Considerable performance deficiencies.	Internal safety concern or public nuisance.		
Poor - Severe defects that will collapse/break in near future.	Major performance deficiencies.	Potential public health, safety, or environmental concern.		
Inoperable - Defects need immediate attention.	Fails to meet performance targets.	Existing threat to public health, safety, or environment.		
	Rating  New or Excellent - None or minor defects.  Good - Defects that have not begun to deteriorate.  Fair - Moderate defects that will continue to deteriorate.  Poor - Severe defects that will collapse/break in near future.	Rating  Rating  Rating  New or Excellent - None or minor defects. Exceeds/Meets all performance targets.  Good - Defects that have not begun to deteriorate. Minor performance deficiencies.  Fair - Moderate defects that will continue to deteriorate. Considerable performance deficiencies.  Poor - Severe defects that will collapse/break in near future. Major performance deficiencies.		

Sewer Treatment Plants									
STP Name	Design Capacity (MGD)	Date Constructed	Major Expansion Date	Condition ID	Performance ID	Priority ID	WRIS PNum		
UNIONTOWN WASTEWATER TREATMENT PLANT	0.16000000	11/30/1969		4					
Treatment Plant Components:									