

WRIS Asset Inventory Report

KY1000050 - Burnside Municipal Water Works

Rating Code	Condition Rating	Performance Rating	Priority Rating
0			Not a priority
1	New or Excellent - None or minor defects.	Exceeds/Meets all performance targets.	It would be nice to have.
2	Good - Defects that have not begun to deteriorate.	Minor performance deficiencies.	Improved system operations & maintenance (O&M) efficiency.
3	Fair - Moderate defects that will continue to deteriorate.	Considerable performance deficiencies.	Internal safety concern or public nuisance.
4	Poor - Severe defects that will collapse/break in near future.	Major performance deficiencies.	Potential public health, safety, or environmental concern.
5	Inoperable - Defects need immediate attention.	Fails to meet performance targets.	Existing threat to public health, safety, or environment.

Water Line Assets

Size (inches)	Material	Decade Constructed	Length (feet)	Condition ID	Performance ID	Priority ID	WRIS PNum
Assessment Area: ANTIOCH SHORES							
3	PVC	1990	29,364	2	2	0	
4	PVC	1990	28,546	2	2	0	
4	PVC	2000	4,259	2	2	0	
6	PVC	1990	13,425	2	2	0	
Assessment Area: BOOK 1							
4	PVC	1960	3,016	4	5	4	WX21199128
4	PVC	1970	2,319	4	5	4	WX21199128
4	PVC	1990	311	2	2	0	
6	PVC	1960	1,938	4	5	4	WX21199128
6	PVC	1980	1,028	3	2	3	
Assessment Area: OLD BURNSIDE							
Up to 2	PVC	2000	294	2	2	0	
3	CAST IRON	1950	301	4	5	4	WX21199128
3	PVC	2000	821	2	2	0	
4	CAST IRON	Prior to 1950	602	4	5	4	WX21199128
4	CAST IRON	1950	3,103	4	5	4	WX21199128
4	PVC	1990	724	2	2	0	
6	CAST IRON	Prior to 1950	10,827	4	5	4	WX21199128
6	CAST IRON	1950	9,716	4	5	4	WX21199128
6	PVC	Prior to 1950	379	3	2	1	
6	PVC	1980	111	2	2	0	
6	PVC	1990	2,999	2	2	0	
6	PVC	2000	11,665	2	2	0	
8	CAST IRON	1950	419	4	5	4	WX21199128
8	PVC	1990	6,310	2	2	0	
8	PVC	2000	2,253	2	2	0	

WRIS Asset Inventory Report

KY1000050 - Burnside Municipal Water Works

Rating Code	Condition Rating	Performance Rating	Priority Rating
0			Not a priority
1	New or Excellent - None or minor defects.	Exceeds/Meets all performance targets.	It would be nice to have.
2	Good - Defects that have not begun to deteriorate.	Minor performance deficiencies.	Improved system operations & maintenance (O&M) efficiency.
3	Fair - Moderate defects that will continue to deteriorate.	Considerable performance deficiencies.	Internal safety concern or public nuisance.
4	Poor - Severe defects that will collapse/break in near future.	Major performance deficiencies.	Potential public health, safety, or environmental concern.
5	Inoperable - Defects need immediate attention.	Fails to meet performance targets.	Existing threat to public health, safety, or environment.

Water Tank Assets

Asset Name	Capacity (gallons)	Date Constructed	Date Inspected	Condition ID	Performance ID	Priority ID	WRIS PNum
Assessment Area: OLD BURNSIDE							
ANTIOCH ROAD WATER TANK	200,000	01/01/1993	01/01/2015	3	2	1	WX21199051

WRIS Asset Inventory Report

KY1000050 - Burnside Municipal Water Works

Rating Code	Condition Rating	Performance Rating	Priority Rating
0			Not a priority
1	New or Excellent - None or minor defects.	Exceeds/Meets all performance targets.	It would be nice to have.
2	Good - Defects that have not begun to deteriorate.	Minor performance deficiencies.	Improved system operations & maintenance (O&M) efficiency.
3	Fair - Moderate defects that will continue to deteriorate.	Considerable performance deficiencies.	Internal safety concern or public nuisance.
4	Poor - Severe defects that will collapse/break in near future.	Major performance deficiencies.	Potential public health, safety, or environmental concern.
5	Inoperable - Defects need immediate attention.	Fails to meet performance targets.	Existing threat to public health, safety, or environment.

Pump Station Assets					
Asset Name	Pump Count	Condition ID	Performance ID	Priority ID	WRIS PNum

WRIS Asset Inventory Report

KY1000050 - Burnside Municipal Water Works

Rating Code	Condition Rating	Performance Rating	Priority Rating
0			Not a priority
1	New or Excellent - None or minor defects.	Exceeds/Meets all performance targets.	It would be nice to have.
2	Good - Defects that have not begun to deteriorate.	Minor performance deficiencies.	Improved system operations & maintenance (O&M) efficiency.
3	Fair - Moderate defects that will continue to deteriorate.	Considerable performance deficiencies.	Internal safety concern or public nuisance.
4	Poor - Severe defects that will collapse/break in near future.	Major performance deficiencies.	Potential public health, safety, or environmental concern.
5	Inoperable - Defects need immediate attention.	Fails to meet performance targets.	Existing threat to public health, safety, or environment.

Water Treatment Plants

WTP Name	Design Capacity (MGD)	Date Constructed	Major Expansion Date	Condition ID	Performance ID	Priority ID	WRIS PNum
BURNSIDE WATER TREATMENT PLANT	0.430	01/01/1948	01/01/1998	2	1	0	

Treatment Plant Components:

--